



# MOTORSPORT SOUTH AFRICA NPC

Reg. No 1995/005605/08

[www.motorsport.co.za](http://www.motorsport.co.za)

2nd Floor, Meersig 1, Cnr. Upper Lake Lane & Constantia Boulevard, Constantia Kloof, Roodepoort. P.O. Box 6677, Weltevreden, 1715  
e-mail: [msa@motorsport.co.za](mailto:msa@motorsport.co.za) Telephone (011) 675 2220 Fax: (011) 675 2219, National Number: 0861 MSA MSA (0861 672 672)

## MSA NATIONAL VW ENGEN POLO CUP CHAMPIONSHIP CIRCULAR 03 OF 2018

The following amendments to the National Polo Cup regulations are made with immediate effect:

### DROPBOX

A dropbox folder will be created for the purpose of "fastest lap" sharing. You will be granted access to this folder and a confirmation email will be send to you in due course. Wimpie will load the fastest lap into this dropbox folder after each session and the driver that has set the fastest lap can come and get the data they want from him with their memory stick.

### GENERAL

The front grill areas next to the VW-Badge may be covered with a mesh, on the backside, to prevent small stones thrown up by other vehicles.



The Alternator cable that runs over the gearbox, runs in an area were the gearbox has a sharp edge. To prevent damage to the cable you may add a sleeve over the cable in this area.

### FRONT BRAKE LINES - SAFETY

Please re-route the front brake lines as shown in the pictures below.

When the wheel is in a certain bump position and steering in full-lock, the tyre touches the fitting which can cause the brake line to come loose.

*MOTORSPORT SOUTH AFRICA IS THE ONLY RECOGNISED MOTORSPORT FEDERATION IN SOUTH AFRICA*



sport & recreation  
Department  
Sport and Recreation South Africa  
REPUBLIC OF SOUTH AFRICA

Directors: Adv. G. T. Avvakoumides (Chairman), A. Scholtz (Chief Executive Officer), A. Taylor (Financial), D. Easom, J. Fourie G. Hall, A. Harri, E. Murray, M. Rowe, R. Schilling, Ms M. Spurr, S. Van der Merwe

**Use all existing plumbing**

Re-route brake line through rubber grommet in wheelarch.



Drill new holes for bulkhead fittings and fasten all plumbing pipes again.



**Driver side:**  
Move fitting to this area

**Passenger side:**  
Move fitting to this area  
above clutch pipe



**WAYNE RIDDELL**  
**SPORTING SERVICES MANAGER**

2<sup>nd</sup> May 2018  
161516/144