Reg. No 1995/005605/08

www.motorsport.co.za

2nd Floor, Meersig 1, Cnr. Upper Lake Lane & Constantia Boulevard, Constantia Kloof, Roodepoort. P.O. Box 6677, Weltevreden, 1715 e-mail: <a href="mailto:msa@motorsport.co.za">msa@motorsport.co.za</a> Telephone (011) 675 2220 Fax: (011) 675 2219

## **MSA SUPERHATCH CIRCULAR 1 OF 2019**

The following amendments to the Superhatch Club Championship Regulations are made with immediate effect:

## 7. Championship Sponsor

f. All series sponsor decals must be in the correct position on all vehicles. The numbers and letters designating the class must be the Committee-specified size/colour and is issued by the committee.

RED (Class A), ORANGE (Class B) and BLUE (Class C)

## Appendix A

- 4. Engine
- Charge coolers may be used, but the water must be supplied by the engine's coolant system. Charge coolers may be replaced by intercoolers. Intercoolers may be upgraded to a larger size. Intercoolers may only be cooled by air no water sprayers allowed. Fitment of intercoolers must be done in such a way so as not to contravene any other rules pertaining to silhouette, body shell, radiator and bumper.

ISSUED BY: ALLISON ATKINSON (MSA SPORT COORDINATOR) ON BEHALF OF THE CHAMPIONSHIP CONTROLLERS

28 March 2019

161869/144

MOTORSPORT SOUTH AFRICA IS THE ONLY RECOGNISED MOTORSPORT FEDERATION IN SOUTH AFRICA













